Project Name: Grand Harbor Field Review
Project Location: Grand Harbor, Vero Beach, Florida

Project Number: 147699000

Date of Study: Summer 2019

Category	Sub Category	No.	ltem	Reference	Unit	Quantity	Cost per Unit	Total Cost
Bridges and Tunnels	Bridge #1	bt1	Replace Bridge #1	16.0 GRAND HARBOR BRIDGE #1 and #2	EA	0	\$800,000	\$0
	Bridge #2	bt2	Bridge #2 Repairs	16.0 GRAND HARBOR BRIDGE #1 and #2	SF	1	\$1,000	\$1,000
	Tunnels	bt3	Tunnel Drainage Improvements (4)	19.0 GRAND HARBOR PEDESTRIAN TUNNELS #1 THROUGH #4	SF	500	\$7	\$3,500
		bt4	General Tunnel Repairs	19.0 GRAND HARBOR PEDESTRIAN TUNNELS #1 THROUGH #4	EA	4	\$750	\$3,000
Bridges and Tunnels Total								\$7,500
Buildings	53rd St	bld6	Guard Shack Repairs/Replacement	Repairs not economical since remaining life is 1 year. Replace	EA	1	\$15,000	\$15,000
	IRB	bld1	Grand Harbor Guard House Repairs	17.0 GRAND HARBOR GUARD HOUSES #1 AND #2	EA	1	\$1,500	\$1,500
		bld2	The Falls Guard House Repairs	17.0 GRAND HARBOR GUARD HOUSES #1 AND #2	EA	1	\$1,500	\$1,500
Buildings Total	l							\$18,000
Conservation Easement	Hydrology	est2	Flushing Channel Repairs - Two Channels	NOT COMPLIANT WITH CONSERVATION EASEMENT OR0922 PG 2192	CY	1,476	\$150	\$221,400
		est3	Water Courses - Narrow	NOT COMPLIANT WITH CONSERVATION EASEMENT OR0922 PG 2192	CY	11,424	\$150	\$1,713,600
		est4	Water Courses - Wide	NOT COMPLIANT WITH CONSERVATION EASEMENT OR0922 PG 2192	CY	29,992	\$150	\$4,498,800
	Plant Removal	est1	Invasive Species Removal - Brazilian Pepper	NOT COMPLIANT WITH CONSERVATION EASEMENT OR0922 PG 2192	DAYS	60	\$5,000	\$300,000
Conservation Easement Total								\$6,733,800
Irrigation	Recycled Water Reservoir	irr1	Pond Liner Fabric Replacement	Needs to be replaced within 5 years and the wood facia requires replacement now. The liner should be replaced now and properly attached to the steel sheet pile behind the wood facia	SF	90,000	\$2	\$180,000
	Recycled Water Reservoir	irr2	Wooden Façade Replacement	18.0 GRAND HARBOR RETAINING WALLS #1 THROUGH #4	EA	1,200	\$70	\$84,000
Irrigation Total								\$264,000

Project Name: Grand Harbor Field Review
Project Location: Grand Harbor, Vero Beach, Florida

Project Number: 147699000

Date of Study: Summer 2019

Category	Sub Category	No.	ltem	Reference	Unit	Quantity	Cost per Unit	Total Cost
Landscaping	Invasive Species Removal	Lsc12	The Falls at Grand Harbor Landscape - Brazilian Pepper	14.0 THE FALLS AT GRAND HARBOR LANDSCAPE	DAYS	2	\$5,000	\$10,000
		Lsc2	45th Street Perimeter Buffer Vines	9.0 GRAND HARBOR 45th STREET PERIMETER BUFFER	LF	600	\$10	\$6,000
		Lsc4	Indian River Boulevard Perimeter Buffer - Vines	10.0 GRAND HARBOR/ OAK HARBOR INDIAN RIVER BOULEVARD PERIMETER BUFFER	LF	500	\$10	\$5,000
	Fence Repair	Lsc5	Indian River Boulevard Perimeter Buffer Perimeter	10.0 GRAND HARBOR/ OAK HARBOR INDIAN RIVER BOULEVARD PERIMETER BUFFER	LF	640	\$15	\$9,600
	Irrigation Pumps and Controllers	irr7	Indian River Boulevard Perimeter Buffer Irrigation Equipment Repairs	10.0 GRAND HARBOR/ OAK HARBOR INDIAN RIVER BOULEVARD PERIMETER BUFFER	EA	1	\$200	\$200
	Tree/Shrub Replacement and Pruning	Lsc1	45th Street Perimeter Buffer	9.0 GRAND HARBOR 45th STREET PERIMETER BUFFER	EA	6	\$100	\$600
		Lsc11	The Falls at Grand Harbor Landscape Tree/Shrub Replacement and Pruning	14.0 THE FALLS AT GRAND HARBOR LANDSCAPE	EA	37	\$287	\$10,619
		Lsc3	Indian River Boulevard Perimeter Buffer	10.0 GRAND HARBOR/ OAK HARBOR INDIAN RIVER BOULEVARD PERIMETER BUFFER	EA	45	\$150	\$6,750
		Lsc6	River Club/Harbor Village R/W Landscape	11.0 RIVER CLUB/ HARBOR VILLAGE R/W LANDSCAPE	EA	11	\$269	\$2,959
		Lsc7	Grand Harbor R/W Landscape	12.0 GRAND HARBOR R/W LANDSCAPE	EA	7	\$95	\$665
		Lsc8	River Village Tract C Stormwater Buffer Landscape	13.0 RIVER VILLAGE TRACT C STORMWATER BUFFER LANDSCAPE	EA	4	\$250	\$1,000
Landscaping Total								\$53,393
Misc	Misc	misc1	River Village Pier Repair	20.0 GRAND HARBOR MISCELLANEOUS STRUCTURES	LF	225	\$200	\$45,000
		misc2	Main Fountain Replace Lighting System and General Repairs	20.0 GRAND HARBOR MISCELLANEOUS STRUCTURES	EA	30	\$300	\$9,000
Misc Total								\$54,000

Project Name: Grand Harbor Field Review
Project Location: Grand Harbor, Vero Beach, Florida

Project Number: 147699000

Date of Study: Summer 2019

Category	Sub Category	No.	ltem	Reference	Unit	Quantity	Cost per Unit	Total Cost
Right of Way	Curbs and Gutters	row8	Replace Curbs and Gutters in 12 locations	4.0 GRAND HARBOR ROADWAYS, CURBS, AND GUTTERS Replace 12 chipped and cracked items	LF	155	\$25	\$3,875
	Guardrails	row3	Replace Guardrails	3.0 GRAND HARBOR SIDEWALKS, GUARDRAILS, AND BULKHEADS 13 items	LF	4,450	\$23	\$102,350
	Lighting	row5	Replace Lighting Fixtures and bury wires	6.0 GRAND HARBOR SITE LIGHTING	EA	14	\$1,000	\$14,000
	Roadways	row10	Full replacement (Subgrade Included) in 7 locations	4.0 GRAND HARBOR ROADWAYS, CURBS, AND GUTTERS Repair 7 locations in poor condition	SY	111	\$45	\$4,995
	Sidewalks	row1	Replace 8x5 Panels after removing any tree roots causing the upheaval of the panels.	3.0 GRAND HARBOR SIDEWALKS, GUARDRAILS, AND BULKHEADS item 14	EA	102	\$280	\$28,560
		row2	Replace Asphalt Sidewalk with a poured concrete sidewalk	3.0 GRAND HARBOR SIDEWALKS, GUARDRAILS, AND BULKHEADS	SY	1,452	\$30	\$43,560
	Signs	row6	Post Replacement (9)	5.0 GRAND HARBOR SIGNAGE	EA	9	\$150	\$1,350
		row7	Sign Replacement (30)	5.0 GRAND HARBOR SIGNAGE	EA	30	\$250	\$7,500
Right of Way Total								\$206,190
Security	Equipment	sec1	Immediate Camera Replacement	7.0 GRAND HARBOR SITE SECURITY	EA	15	\$200	\$3,000
Security Total								\$3,000

Project Name: Grand Harbor Field Review

Project Location: Grand Harbor, Vero Beach, Florida

Project Number: 147699000

Date of Study: Summer 2019

Category	Sub Category	No.	ltem	Reference	Unit	Quantity	Cost per Unit	Total Cost
3	Exfil Trenches	swm8	St Andrews Exfiltration Trench Replacement	Not compliant with SJRWMD 18679 Permit Condition and FEDP 311043029 Permit Condition	LF	890	\$125	\$111,250
	Ponds	swm1	Pond Bank Restoration (Single Bag)	Not compliant with SJRWMD 18679 Permit Condition and FEDP 311043029 Permit Condition	LF	54,107	\$50	\$2,705,350
		swm1.1	Pond Bank Restoration (Double Bag)	Not compliant with SJRWMD 18679 Permit Condition and FEDP 311043029 Permit Condition	LF	2,200	\$80	\$176,000
		swm3	St Andrews Pond Rebuild	Not compliant with SJRWMD 18679 Permit Condition and FEDP 311043029 Permit Condition	EA	1	\$20,000	\$20,000
		swm4	Storm Pipe Lining	8.0 GRAND HARBOR PONDS	LF	80	\$200	\$16,000
		swm5	Storm Pipe cutoff and replace	8.0 GRAND HARBOR PONDS	EA	3	\$8,600	\$25,800
		swm6	Littoral Zone Planting	Not compliant with SJRWMD 18679 Permit Condition and FEDP 311043029 Permit Condition	SF	719,393	\$5	\$3,596,965
		swm7	Replace the aeration system	Not compliant with SJRWMD 18679 Permit Condition and FEDP 311043029 Permit Condition	EA	1	\$7,500	\$7,500
Stormwater Management Total								\$6,658,865
Walls	Bulkheads	wal1	Replace Bulkhead #3	3.0 GRAND HARBOR SIDEWALKS, GUARDRAILS, AND BULKHEADS 13 items	EA	1	\$7,500	\$7,500
	River Village Retaining Wall (Retaining Wall #5)	wal2	Retaining Wall #3 Wooden Façade Replair	18.0 GRAND HARBOR RETAINING WALLS #1 THROUGH #4	LF	330	\$70	\$23,100
Walls Total								\$30,600

Grand Total \$14,029,348